


# INDUSTRIAL SENSOR CROSS REFERENCE CHART

*Partial listing. Contact Ventrex for additional information.*

| Manufacturer    | Sensor No. | Sensors  |
|-----------------|------------|----------|
| City Technology | 4CO        | V40 CO   |
|                 | 4CF        | V40 CO/F |
|                 | 4H         | V40H2S/H |
|                 | 4HS        | V40H2S   |
|                 | 4OX-1      | V4002-1  |
|                 | 4OX-2      | V4002-2  |
|                 | 7E/F       | V70CO/F  |
|                 | 7E         | V70CO    |
|                 | 7H         | V70H2S   |
|                 | 7HH        | V70H2S/H |

| Manufacturer | Sensor No. | Sensors  |
|--------------|------------|----------|
| Alphasense   | CO-AF      | V40 CO/F |
|              | H2S-A1     | V40H2S   |
|              | O2-A1      | V4002-1  |
|              | O2-A2      | V4002-2  |
|              | CO-BF      | V70CO/F  |
|              | H2S-B1     | V70H2S   |



Ventrex, Inc. • 159 Gibraltar Road • Horsham, PA 19044  
215-675-7714 • fax 215-675-7851 • www.ventrexsensors.com • e-mail: info@ventrexsensors.com